

**Photographs – Franklin Branch Streambank Stabilization (Courtesy HRC)**



**Photograph 1:** Threatened sanitary sewer line in Area 2



**Photograph 2:** Streambank erosion in Area 2, facing downstream



**Photograph 3:** Streambank erosion in Area 2, facing upstream

**Photographs – Franklin Branch Streambank Stabilization (Courtesy HRC)**



**Photograph 4:** Upper slope failure in Area 2 (1)



**Photograph 5:** Upper slope failure in Area 2 (2)



**Photograph 6:** Runoff from north side of the floodplain

**Photographs – Franklin Branch Streambank Stabilization (Courtesy HRC)**



**Photograph 7:** Upper slope failure in Area 3 along 14 Mile Road



**Photograph 8:** Upper slope failure in Area 3 below 14 Mile Road



**Photograph 9:** Streambank erosion in Area 4, facing upstream

**Photographs – Franklin Branch Streambank Stabilization (Courtesy HRC)**



**Photograph 10:** Base of slope failure in Area 4



**Photograph 11:** Upper slope failure in Area 4 below 14 Mile Road